

## Invoice 134307

### Invoice

S78-018 – Additional Items



PR  
NAUTICA

Date | 28 January 2022  
Invoice Number | 134307

Invoice Total | £57,658.30

Balance | £0.00

From | PR Nautica Ltd.  
Eastern Hangar, Lawrence  
Road  
Plymouth, Devon PL9 9SJ  
GB  
  
To | Vitaly Baranov  
Apartment 63  
House 12  
Voskresenskaya Embankment  
St. Petersburg, 191123  
RU

Task	Rate	Qty	Amount
<b>Icemaker</b> To supply and fit icemaker in Flybridge wetbar	£1,775.00	1	£1,775.00
<b>Additional Underwater Lights</b> To install x2 extra underwater lights to make total x3 lights on both side of cockpit	£885.00	1	£885.00
<b>Lifesaving Kit</b> To supply liferaft 12 man ISO9650 solas b pack type 1	£2,475.00	1	£2,475.00
To supply adult Commodore blue, auto gas inflate lifejackets x12 with light	£870.00	1	£870.00
To supply 1 x Icom M23 waterproof hand held VHF	£155.00	1	£155.00

To supply a 3Si Guardian cat 1 GPS EPIRB	£425.00	1	£425.00
To supply Seasafe SART	£475.00	1	£475.00
To supply plastimo marine 7×50 autofocus binoculars	£60.00	1	£60.00
To supply admiralty paper chart 1578 for Croatia and Montenegro	£35.00	1	£35.00
To supply and fit 24v digital Meteomam barometer to helm side pillar	£345.00	1	£345.00
<b>Water filters</b> To supply and fit a UV sterilizer and x2 cartridge filters (has a 5micron filter, 20micron and carbon block filter) to the water system to filter all water taken from the fresh water tank. This system can handle the vessels water flow rate and therefore filter the water on exit from pump while not reducing vessels water pressure. This system will filter all water going to the water network, i.e. Sink taps, showers, icemaker, washing machine	£1,825.00	1	£1,825.00
<b>Spare filters for water treatment system</b> To supply the following spare water filters: 2 x 5-micron filters	£86.00	1	£86.00
2 x 20 micron granular carbon filters	£154.00	1	£154.00
2 x Carbon block filters	£90.00	1	£90.00
<b>Spares</b> To supply 5lts of princess white gel coat	£30.00	1	£30.00

Supply x10 spare locker push push catches	£55.00	1	£55.00
<b>Generator spares kit</b> To supply Onan Generator spares kit, containing oil filter, oil, impeller kit	£430.00	1	£430.00
<b>Man Engine spares kit</b> Supply an engine spares kit, as recommended by MAN consisting of: <ul style="list-style-type: none"> <li>• 2x Oil Filters</li> <li>• 2x Fuel filter inserts and seal</li> <li>• 2x Fuel filter elements</li> <li>• 2 x CU seals -Fuel bleed</li> <li>• 1 x Sea water pump impellers</li> <li>• 1x Ribbed V-belts</li> <li>• 1 x Impeller extraction tool</li> </ul>	£2,225.00	1	£2,225.00
<b>Engine oil</b> To supply MAN engine oil (20l)	£82.80	1	£82.80
Supply 10ltrs of 46 grade hydraulic system oil for platform / Passerelle	£62.00	1	£62.00
Supply 10 ltrs of steering oil	£77.00	1	£77.00
Supply 5 ltrs of trim tab oil	£60.00	1	£60.00
<b>Spare bulbs</b> X5 24v-6W LED down lights	£375.00	1	£375.00
X15 white exterior LED deck lights	£245.00	1	£245.00

<b>Seabobs</b> To supply x2 Seabob F5S units (colours as chosen), delivered to Plymouth Cost £19,112.00 X2 Seabob racks Cost £445.00 X2 quick chargers Cost £2830.00 Deliver to Plymouth Cost £750.00 Total retail £23,137.00 less 10% discount = £20,824.00 (this price only valid until 15 Dec as Seabob have 8% price increase due then)	£20,824.00	1	£20,824.00
<b>Service generator</b> To complete ONAN annual service to generator	£850.00	1	£850.00
<b>Polish hull and stainless</b> To cut and polish hull in full and detail all stainless	£3,250.00	1	£3,250.00
<b>Replace generator battery</b> To replace generator battery with new	£175.00	1	£175.00
<b>Fender socks</b> To supply x20 grey fender socks	£510.00	1	£510.00
<b>Fender lines</b> To supply x12 new fender lines	£137.00	1	£137.00
<b>Lava brick BBQ bricks</b> To supply bag of Kenyon BBQ bricks for bbq	£27.50	1	£27.50
<b>Glasses</b> To supply x2 new whisky tumblers	£170.00	1	£170.00
To supply x1 new wine glass	£46.00	1	£46.00

<b>Stainless steel backlite name</b>	£2,855.00	1	£2,855.00
To supply and fit mirror polished 316 stainless steel name with backlighting single ice white colour 'VOLGA'			
<b>Repair items</b>	£1,850.00	1	£1,850.00
Cleaning – To clean the following items – Exterior flybridge cushions, flybridge helm seats, interior carpets, saloon sofas, Bimini. Any areas that cannot be brought back to suitable new like condition to report and quote for replacement			
<b>Paint repairs general</b>	£1,725.00	1	£1,725.00
To provide a painter for 5 days to walk through interior of vessel and make repairs to noted wood damage to furniture			
Upper helm seating wood flooring to strip and re varnish	£675.00	1	£675.00
Respray in oyster grey both aft cockpit sunbed surrounds where damage has occurred, plus repair paint damage on side coaming where cockpit covers have damaged and respray area around hard-top sunroof which has been damaged	£2,850.00	1	£2,850.00
Re seal side door and repair gel coat damage around frame to prevent water leaks	£877.00	1	£877.00
Master cabin stbd side top window pelmet to remove and recover, if cannot be cleaned of yellow staining	£1,475.00	1	£1,475.00
Secure feature panel that's loose below port side console	£320.00	1	£320.00
Remove, strip and recover both port and stbd black mullions	£1,095.00	1	£1,095.00
Master cabin vanity door hinge repair, plus lower helm lift up chart locker hinge repair	£165.00	1	£165.00

Service sliding roof, check motor and grease all carts and cables	£350.00	1	£350.00
Service all aircon blowers, cleaning filters and drains	£200.00	1	£200.00
Repair gel coat cracks to both sides of aft fairleads	£985.00	1	£985.00
Repair Bimini lights cable	£275.00	1	£275.00
Repair port windscreen wiper	£200.00	1	£200.00
Repair failed toilet flush in stbd heads	£685.00	1	£685.00
To replace two teak nosings on cockpit steps that have split and fair back in step facias	£1,255.00	1	£1,255.00
To install poppers for saloon sofa backs	£75.00	1	£75.00
Check and adjust all door handles, catches (interior and exterior)	£0.00	1	£0.00
<b>Port of Registry</b> To supply and fit black vinyl letters 'Port of Peel'	£75.00	1	£75.00
<b>Williams Tender Service</b> To complete general service to Williams 385 including oil change, oil filter and fuel filter replacement.	£385.00	1	£385.00

Subtotal	£57,658.30
Payment Service Fee	£0.00
<b>Total ?</b>	<b>£57,658.30</b>
Payments	£57,658.30
Balance	£0.00

## Terms

Please note our terms of business that apply, as per British Marine Federation Terms of Business Edition 15a.

Our full terms and conditions can be found at <https://prnautica.com/terms-of-business/>

	Pound Sterling (£)	Euro (€)
<b>Account Name:</b>	PR Nautica Ltd.	
<b>Account Number:</b>	23222691	46975188
<b>Sort Code:</b>	20-68-10	20-68-10
<b>IBAN:</b>	GB73 BUKB 2068 1023 2226 91	GB94 BUKB 2068 1046 9751 88
<b>BIC:</b>	BUKBGB22	BUKBGB22

Registered in England 05692821, VAT No. 878 3861 63, EORI No. GB878386163000

 <https://prnautica.com>  [web@prnautica.com](mailto:web@prnautica.com)

